


1968 W1SS

PARTS DIAGRAM

CHASSIS ELECTRICAL EQUIPMENT



1968 W1SS

PARTS LIST

CHASSIS ELECTRICAL EQUIPMENT

ITEM NAME	PART NUMBER	QUANTITY
GROMMET HARNESS 10MM (Ref # 1)	92071-019	1
GROMMET HARNESS 10MM (Ref # 2)	92071-010	1
WIRING HARNESS REAR (Ref # 3)	26002-010	1
WIRING HARNESS MAIN (Ref # 4)	26001-026	1
WIRING HARNESS MAIN (Ref # 5)	26001-027	1
WIRE REGURATOR (Ref # 7)	26002-009	(1
WIRE REGULATOR LEAD (Ref # 7)	26002-013	1
BAND RUBBER (Ref # 8)	92072-013	10
BAND RUBBER (Ref # 9)	92072-018	3
HOUSING IGNITION SW (Ref # 10)	27009-002	1
SWITCH ASSY IGNITION (Ref # 11,12)	27005-016	1
KEY SET IGN NO.651 (Ref # 12)	27008-020-51	1
KEY SET IGN NO.652 (Ref # 12)	27008-020-52	1
KEY SET IGN.NO.653 (Ref # 12)	27008-020-53	1
KEY SET IGN NO.654 (Ref # 12)	27008-020-54	1
KEY SET IGN NO.655 (Ref # 12)	27008-020-55	1
KEY SET IGN NO.656 (Ref # 12)	27008-020-56	1
KEY SET IGN NO.657 (Ref # 12)	27008-020-57	1
KEY SET IGN NO.658 (Ref # 12)	27008-020-58	1
SCREW PAN HEAD 6X16 (Ref # 13)	220B0616	2
WASHER PLAIN 6MM (Ref # 14)	410B0600	2
WASHER SPRING 6MM (Ref # 15)	461F0600	2
NUT 6MM (Ref # 16)	311B0600	2
YUA BAT 12N7-3B (Ref # 17,18)	K26012-016	1
SCREW BATTERY TERMNAL (Ref # 18)	26013-002	2
FUSE ASSY (Ref # 22,23)	26004-026	(1
FUSE ASSY (Ref # 22,23)	26004-005	1
FUSE 10A (Ref # 23)	26006-001	(2
FUSE 20A (Ref # 23)	26006-002	2

1968 W1SS

PARTS LIST

CHASSIS ELECTRICAL EQUIPMENT

ITEM NAME	PART NUMBER	QUANTITY
LEAD WIRE B (Ref # 24)	26011-016	1
LEAD WIRE A (Ref # 25)	26011-015	1
WIRE BATTERY LEAD (Ref # 26)	26010-016	1
WIRE BATTERY GROUND (Ref # 27)	26010-017	1
CAP BAT TERMINAL RUBB (Ref # 28)	92073-001	1
CAP IGNITION COIL (Ref # 29)	92073-003	3