

1975 Mach IV

PARTS DIAGRAM

TURN SIGNALS (H2-B/C)

NO IMAGE AVAILABLE

1975 Mach IV

PARTS LIST

TURN SIGNALS (H2-B/C)

ITEM NAME	PART NUMBER	QUANTITY
LAMP ASSY,TURN SIGNAL (Ref # 1)	23040-034	
SCREW-PAN HEAD,4X35 (Ref # 2)	220E0435A	
WASHER-PLAIN,4MM (Ref # 3)	23058-002	
LENS-SIGNAL LAMP (Ref # 4)	23048-1024	
LENS-SIGNAL LAMP (Ref # 4)	23048-1024	
GASKET,TURN SIG LAMP (Ref # 5)	23050-002	
BULB 12V 32CP (Ref # 6)	92069-055	
UNAVAILABLE IN PRICE BOOK (Ref # 7)	110N0630-	
WASHER PLAIN 6MM (Ref # 8)	411B0600	
WASHER SPRING 6MM (Ref # 9)	461F0600	
NUT 6MM (Ref # 10)	311B0600	
BRACKET-TURN SIG LAMP (Ref # 11)	23078-001	
BOLT SET-SIG LAMP BKT (Ref # 12)	23073-001	
DAMPER RUBBER (Ref # 13)	92075-128	
NUT 10MM (Ref # 14)	315B1000	
DAMPER RUBBER,SIG LM (Ref # 15)	92075-158	
COLLAR (Ref # 16)	23076-004	
WASHER SPRING 10MM (Ref # 17)	461F1000	