


1982 KZ1000-J2

PARTS DIAGRAM

CABLES

F2540-0140



1982 KZ1000-J2

PARTS LIST

CABLES

ITEM NAME	PART NUMBER	QUANTITY
CABLE-CLUTCH (Ref # 54011)	54011-1147	1
CABLE-THROTTLE (Ref # 54012A)	54012-1110	1
CLAMP,CABLE (Ref # 92037)	92037-093	1
CLAMP (Ref # 92037B)	92037-1250	1
CLAMP (Ref # 92037C)	92037-1251	1
CLAMP (Ref # 92037D)	92037-1252	1