


1983 KZ1000-J3

PARTS DIAGRAM

CABLES

F2540-0140



1983 KZ1000-J3

PARTS LIST

CABLES

ITEM NAME	PART NUMBER	QUANTITY
CABLE,SPEEDOMETER (Ref # 54001)	54001-1014	1
CABLE-CLUTCH (Ref # 54011A)	54011-1136	1
CABLE-THROTTLE (Ref # 54012B)	54012-1111	1
CLAMP,CABLE (Ref # 92037)	92037-093	1
CLAMP,THROTTLE CABLE (Ref # 92037A)	92037-1189	1
CLAMP (Ref # 92037D)	92037-1252	1