


1973 F12MX

PARTS DIAGRAM

SWING ARM/SHOCK ABSORBERS ('73 F12MX 450)



1973 F12MX

PARTS LIST

SWING ARM/SHOCK ABSORBERS ('73 F12MX 450

ITEM NAME	PART NUMBER	QUANTITY
ARM,SWINGING (Ref # 1)	33001-056	1
SHAFT,SWING ARM PIVO (Ref # 2)	33032-042	1
BUSHING,SWING ARM (Ref # 3)	33033-012	2
ADJUSTER,CHAIN (Ref # 4)	33040-055	2
PLATE,CHAIN ADJUSTER (Ref # 5)	33041-003	2
NUT,12MM (Ref # 6)	92019-017	1
NUT,8MM (Ref # 7)	92019-018	6
GUARD,CHAIN (Ref # 8)	55020-011	1
BOLT,8X55 (Ref # 9)	92001-1386	2
WASHER PLAIN 8MM (Ref # 10)	411B0800	4
COLLAR,CHAIN GUARD (Ref # 11)	92027-196	1
SHOCK ABSBR RR (Ref # 12)	45014-087	2
PIN,SWING ARM (Ref # 13)	92043-099	2
CIRCLIP 10MM (Ref # 14)	482J0100	2
WASHER-PL-10.5X26X2. (Ref # 15)	92022-044	1
NUT,10MM (Ref # 16)	92019-016	2
TORQUE LINK,REAR (Ref # 17)	43007-038	1
PIN,TORQUE LINK (Ref # 18)	92043-100	1
CIRCLIP 10MM (Ref # 19)	482J0100	1
BOLT,TORQUE LINK FIT (Ref # 20)	92003-136	1