



# 2004 KDX200

## PARTS DIAGRAM

Meter(s)

F2530



# 2004 KDX200

## PARTS LIST

Meter(s)



| ITEM NAME                            | PART NUMBER | QUANTITY |
|--------------------------------------|-------------|----------|
| NUT-HEX (Ref # 311)                  | 311B0400    | 2        |
| SPEEDOMETER,TRIP(MILE) (Ref # 25005) | 25005-1573  | 1        |
| BRACKET-METER (Ref # 25008)          | 25008-1196  | 1        |
| WASHER,4.3X12.5X1 (Ref # 92022)      | 92022-1888  | 2        |
| KNOB,TRIP (Ref # 92077)              | 92077-1114  | 1        |
| DAMPER (Ref # 92160)                 | 92160-1569  | 1        |