


1991 KDX250

PARTS DIAGRAM

Cables

F 2 5 4 0



1991 KDX250

PARTS LIST

Cables

ITEM NAME	PART NUMBER	QUANTITY
BOOT (Ref # 49006)	49006-1189	1
CABLE-SPEEDOMETER (Ref # 54001)	54001-1170	1
CABLE-CLUTCH (Ref # 54011)	54011-1310	1
CABLE-THROTTLE (Ref # 54012)	54012-1410	1
CLAMP,CABLE (Ref # 92037)	92037-1064	1