


# 1991 KE100

## PARTS DIAGRAM

### Generator

E1810-0036



# 1991 KE100

## PARTS LIST

### Generator

| ITEM NAME                          | PART NUMBER | QUANTITY |
|------------------------------------|-------------|----------|
| HOLDER,OIL FELT (Ref # 13091)      | 21038-002   | 1        |
| STATOR (Ref # 21003)               | 21003-1014  | 1        |
| BREAKER,CONTACT (Ref # 21008)      | 21008-006   | 1        |
| CONDENSER (Ref # 21013)            | 21013-006   | 1        |
| BRUSH,OIL (Ref # 21039)            | 21019-005   | 1        |
| PLATE-COIL,MAGNETO (Ref # 21048)   | 21048-007   | 1        |
| COIL-EXCITING (Ref # 21049)        | 21049-1004  | 1        |
| FLYWHEEL,MAGNETO (Ref # 21050)     | 21050-1009  | 1        |
| REGULATOR-VOLTAGE (Ref # 21066)    | 21066-1012  | 1        |
| HARNESS,MAGNETO (Ref # 26001)      | 26001-1077  | 1        |
| COIL-CHARGING,A (Ref # 59031)      | 59031-1001  | 1        |
| COIL-CHARGING,B (Ref # 59031A)     | 59031-1002  | 1        |
| CLAMP,WIRING HARNESS (Ref # 92037) | 21037-002   | 1        |
| GROMMET (Ref # 92071)              | 21017-002   | 1        |
| BOLT-UPSET-WSP (Ref # 187)         | 187B0625    | 1        |
| SCREW-PAN-CROS,4X6 (Ref # 220)     | 220B0406    | 3        |
| SCREW-PAN-CROS,4X12 (Ref # 220A)   | 220B0412    | 1        |
| SCREW-PAN-CROS (Ref # 220B)        | 220E0430    | 6        |
| SCREW-CSK-CROS,6X14 (Ref # 221)    | 221B0614    | 2        |
| WASHER-SPRING,4MM (Ref # 461)      | 461F0400    | 9        |