


2000 Lakota 300

PARTS DIAGRAM

Transmission



2000 Lakota 300

PARTS LIST

Transmission

ITEM NAME	PART NUMBER	QUANTITY
SHAFT-TRANSMISSION INPUT,11T (Ref # 13127)	13127-1127	1
SHAFT-TRANSMISSION OUTPUT (Ref # 13128)	13128-1201	1
GEAR,OUTPUT LOW,34T (Ref # 13129)	13129-1683	1
GEAR-REVERSE,26T (Ref # 13129A)	13129-1688	1
SPROCKET-OUTPUT,12T (Ref # 13144)	13144-1255	1
GEAR,INPUT 2ND,15T (Ref # 13260)	13260-1437	1
GEAR,INPUT TOP&3RD,25T&18T (Ref # 13260A)	13260-1438	1
GEAR,INPUT 4TH,22T (Ref # 13260B)	13260-1439	1
GEAR,OUTPUT 2ND,31T (Ref # 13260C)	13260-1440	1
GEAR,OUTPUT 3RD,27T (Ref # 13260D)	13260-1441	1
GEAR,OUTPUT 4TH,25T (Ref # 13260E)	13260-1442	1
GEAR,OUTPUT TOP,22T (Ref # 13260F)	13260-1443	1
NUT,20MM (Ref # 92015)	92015-1963	1
WASHER,22.3X27X0.5 (Ref # 92022)	92022-198	7
WASHER,17.3X28X1 (Ref # 92022A)	92022-255	1
WASHER,17.3X30X1.4 (Ref # 92022B)	92022-270	1
RING-SNAP,20X25.5X1.2 (Ref # 92033)	92033-025	6
RING-SNAP (Ref # 92033A)	92033-032	2
BEARING-NEEDLE,K17X23X13.8 (Ref # 92046)	92046-1184	2
RING-O,21.5MM (Ref # 92055)	92055-1293	1
COLLAR (Ref # 92143)	92143-1706	1
WASHER (Ref # 92200)	92200-1065	1