



# 2007 Z1000

## PARTS DIAGRAM

### Crankcase Bolt Pattern

E1412



# 2007 Z1000

## PARTS LIST

### Crankcase Bolt Pattern



| ITEM NAME                        | PART NUMBER | QUANTITY |
|----------------------------------|-------------|----------|
| BOLT,FLANGED,7X85 (Ref # 92150)  | 92150-1251  | 3        |
| BOLT,8X70 (Ref # 92150A)         | 92150-1483  | 2        |
| BOLT,6X60 (Ref # 92150B)         | 92150-1548  | 2        |
| BOLT,6X90 (Ref # 92150C)         | 92150-1622  | 2        |
| BOLT,6X40 (Ref # 92150D)         | 92150-1794  | 3        |
| BOLT,9X81 (Ref # 92151)          | 92151-1222  | 6        |
| BOLT,FLANGED,7X50 (Ref # 92151A) | 92151-1223  | 1        |
| BOLT,FLANGED,9X95 (Ref # 92151B) | 92151-1378  | 4        |
| BOLT,FLANGED,7X45 (Ref # 92151C) | 92151-1539  | 6        |
| WASHER,9.2X19X23 (Ref # 92200)   | 92200-0115  | 4        |