

2007 Z1000

PARTS DIAGRAM

Throttle

Let the Good Times Roll®

E1510



2007 Z1000

PARTS LIST

Throttle

ITEM NAME	PART NUMBER	QUANTITY
BOLT-FLANGED,5X8 (Ref # 130)	130G0508	1
SCREW-PAN-WS-CROS,4X10 (Ref # 223)	223D0410	2
CAP (Ref # 11065)	11065-0018	4
PLATE (Ref # 13271)	13271-0056	1
SCREW-PILOT AIR (Ref # 16014)	16014-0002	4
SCREW-THROTTLE STOP (Ref # 16021)	16021-0017	1
INSULATOR (Ref # 16073)	16073-3707	4
THROTTLE-ASSY,TTK36 (Ref # 16163)	16163-0079	1
LINK-ASSY (Ref # 16170)	16170-0005	1
HARNESS (Ref # 26031)	26031-0313	1
PIPE-COMP,FUEL (Ref # 31064)	31064-0101	1
NOZZLE-INJECTION (Ref # 49033)	49033-0012	4
PIPE-INJECTION (Ref # 49056)	49056-0001	2
JOINT,4WAY (Ref # 59071)	59071-0014	1
JOINT,3WAY,T (Ref # 59071A)	59071-3752	1
BOLT,THROTTLE ADJUST (Ref # 92001)	92001-1998	1
SCREW,5X10 (Ref # 92009)	92009-1502	1
RING-O,INJECTION NOZZLE (Ref # 92055)	92055-1622	4
BAND,SUB-HARNESS (Ref # 92072)	92072-0012	2
SPRING (Ref # 92081)	92081-1620	2
SPRING (Ref # 92144)	92144-1451	1
SCREW,PIPE INJECTION (Ref # 92172)	92172-0064	4
SCREW (Ref # 92172A)	92172-0321	1
TUBE,3X7X30 (Ref # 92191)	92191-0025	2
TUBE,3X7X82 (Ref # 92191A)	92191-0036	1
TUBE,3X7X95 (Ref # 92192)	92192-0018	2
TUBE,3X7X170 (Ref # 92192A)	92192-0019	1