


2000 Prairie 400

PARTS DIAGRAM

Generator

E1810



2000 Prairie 400

PARTS LIST

Generator



ITEM NAME	PART NUMBER	QUANTITY
BOLT-SOCKET,6X30 (Ref # 120)	120P0630	3
BOLT-UPSET-WS,6X30 (Ref # 180)	180D0630	2
SCREW-PAN-CROS,6X10 (Ref # 220)	220B0610	1
KEY-WOODRUFF (Ref # 510)	510A4200	1
PLATE,HARNESS (Ref # 13169)	13169-1788	1
STATOR (Ref # 21003)	21003-1345	1
ROTOR,GENERATOR (Ref # 21007)	21007-1306	1
REGULATOR-VOLTAGE (Ref # 21066)	21066-1112	1