

Swingarm

Let the Good Times Roll®

Exploded view diagram of a vehicle chassis assembly. The diagram shows the main chassis frame (33001) and various suspension and steering components. A "FRONT" arrow points to the left. The components and their part numbers are:

- 33032 (Long axle)
- 11012 (Washers)
- 42036 (Bushing)
- 92046 (Bushing)
- 92210 (Nut)
- 11012 (Washer)
- 42036 (Bushing)
- 92046 (Bushing)
- 11012 (Washer)
- 33001 (Main chassis frame)
- 92172 (Bolt)
- 92143 (Washer)
- 12053B (Bracket)
- 13270 (Bracket)
- 92009 (Bolt)
- 92015 (Nut)
- 92001 (Bolt)
- 33040 (Bracket)
- 12053A (Bracket)
- 12053 (Bracket)
- 13272 (Bracket)
- 132 (Bolt)
- 221 (Bolt)

2014 KX™100

PARTS LIST

Swingarm



ITEM NAME	PART NUMBER	QUANTITY
-----------	-------------	----------