



2001 KX100

PARTS DIAGRAM

Labels

F2860



2001 KX100

PARTS LIST

Labels



ITEM NAME	PART NUMBER	QUANTITY
LABEL,32:1 (Ref # 56030B)	56030-1230	1
LABEL,IMPORTANT NOTICE (Ref # 56030)	56030-1228	1
LABEL,DISCLAIMER (Ref # 56030A)	56030-1229	1
LABEL,NOISE EMISSION (Ref # 56030C)	56030-1231	1
LABEL,DISCLAIMER (Ref # 56030D)	56030-1233	1