


2001 KX100

PARTS DIAGRAM

Decals(D1)

F2861



2001 KX100

PARTS LIST

Decals(D1)



ITEM NAME	PART NUMBER	QUANTITY
MARK,SWING ARM,LH,KX100 (Ref # 56052)	56052-1281	1
MARK,SWING ARM,RH,KX100 (Ref # 56052A)	56052-1282	1
PATTERN,SHROUD,LH (Ref # 56063)	56063-1814	1
PATTERN,SHROUD,RH (Ref # 56063A)	56063-1815	1