


1991 KX500

PARTS DIAGRAM

Step

F2160



1991 KX500

PARTS LIST

Step



ITEM NAME	PART NUMBER	QUANTITY
BRACKET-STEP (Ref # 32054)	32054-1168	1
STEP,LH (Ref # 34028B)	34028-1318	1
STEP,RH (Ref # 34028C)	34028-1319	1
PIN,10X45.5 (Ref # 92043)	92043-1372	2
SPRING,STEP,LH (Ref # 92144)	92144-1511	1
SPRING,STEP,RH (Ref # 92144A)	92144-1512	1
BOLT,SOCKET,10X20 (Ref # 92150)	92150-1255	2
PIN-COTTER,3.0X20 (Ref # 550)	550D3020	2