


2001 KX65

PARTS DIAGRAM

Swingarm

Kawasaki
Let the Good Times Roll®

F2141



2001 KX65

PARTS LIST

Swingarm

Kawasaki

Let the Good Times Roll®

ITEM NAME	PART NUMBER	QUANTITY
SCREW-PAN-CROS,5X8 (Ref # 220)	220B0508	2
NUT-HEX,6MM (Ref # 311)	311B0600	2
CAP (Ref # 11012)	11012-1263	4
GUIDE-CHAIN,FR (Ref # 12053)	12053-1435	1
GUIDE-CHAIN,RR (Ref # 12053A)	12053-1436	1
GUIDE,CHAIN (Ref # 13070)	13070-1347	1
ARM-COMP-SWING,SILVER (Ref # 33001)	33001-1598-TX	1
SHAFT-SWING ARM (Ref # 33032)	33032-1194	1
ADJUSTER-CHAIN (Ref # 33040)	33040-1182	2
SLEEVE,SWING ARM,L=34 (Ref # 42036)	42036-1067	2
BOLT,6X39 (Ref # 92001)	92001-1463	2
BOLT,FLANGED,6X48 (Ref # 92003)	92003-179	2
NUT,FLANGED,12MM (Ref # 92015)	92015-1433	1
BEARING-NEEDLE (Ref # 92046)	92046-1046	2
COLLAR (Ref # 92143)	92143-1676	2
COLLAR (Ref # 92152)	92152-1215	2