

PARTS DIAGRAM

Throttle(A2H/A3H)

Let the Good Times Roll®

FRONT

16163/A

92072

26031

92072

92192

59071A

92191

92192A

92191A

59071

92191

92192

92001

92081

92144

A

92172

49056

31064

92153

14091

99999

(UK, WV) (OPTION)

16170

223

16021

92081

92172A

16014

16073

49033

92055

92172B

21176A

92055A

21176

130

13271

92153

B

C

14091

2005 Z1000 (European)

PARTS LIST

Throttle(A2H/A3H)

ITEM NAME	PART NUMBER	QUANTITY
BOLT-FLANGED (Ref # 130)	130G0508	1
SCREW-PAN-WS-CROS (Ref # 223)	223D0410	2
CAP (Ref # 11065)	11065-0018	2
PLATE (Ref # 13271)	13271-0056	1
COVER,THROTTLE-BODY (Ref # 14091)	14091-0055	2
SCREW-PILOT AIR (Ref # 16014)	16014-0002	4
SCREW-THROTTLE STOP (Ref # 16021)	16021-0002	1
INSULATOR (Ref # 16073)	16073-3707	4
LINK-ASSY (Ref # 16170)	16170-0004	1
SENSOR,TPS (Ref # 21176)	21176-0002	1
SENSOR,TPS (Ref # 21176A)	21176-0003	1
HARNESS (Ref # 26031)	26031-0040	1
PIPE-COMP (Ref # 31064)	31064-0005	1
NOZZLE-INJECTION (Ref # 49033)	49033-1060	4
PIPE-INJECTION (Ref # 49056)	49056-0001	2
JOINT,4WAY (Ref # 59071)	59071-0014	1
JOINT,3WAY,T (Ref # 59071A)	59071-3752	2
BOLT,THROTTLE ADJUST (Ref # 92001)	92001-1998	1
RING-O,INJECTION NOZZLE (Ref # 92055)	92055-1622	4
RING-O (Ref # 92055A)	92055-1671	2
BAND,SUB-HARNESS (Ref # 92072)	92072-0012	3
SPRING (Ref # 92081)	92081-1620	2
SPRING (Ref # 92144)	92144-1451	1
BOLT,SOCKET,5X16 (Ref # 92153)	92153-1244	2
SCREW,PIPE INJECTION (Ref # 92172)	92172-0064	4
SCREW,THROTTLE SYNCRO (Ref # 92172A)	92172-0065	1
SCREW (Ref # 92172B)	92172-0080	2
TUBE,3X7X30 (Ref # 92191)	92191-0025	3
TUBE,3X7X82 (Ref # 92191A)	92191-0036	1

2005 Z1000 (European)

PARTS LIST

Throttle(A2H/A3H)



ITEM NAME	PART NUMBER	QUANTITY
TUBE,3X7X265 (Ref # 92191B)	92191-0038	1
TUBE,3X7X95 (Ref # 92192)	92192-0018	2
TUBE,3X7X170 (Ref # 92192A)	92192-0019	1
TUBE,3X7X275 (Ref # 92192B)	92192-0062	1
THROTTLE-ASSY (Ref # 16163)	16163-0032	1
THROTTLE-ASSY (Ref # 16163A)	16163-0034	1
KIT.,72KW (Ref # 99999)	99999-0005	1