


2026 Z1100 SE ABS

PARTS DIAGRAM

Transmission



2026 Z1100 SE ABS

PARTS LIST

Transmission

ITEM NAME	PART NUMBER	QUANTITY
SHAFT-TRANSMISSION INPUT,15T (Ref # 13127)	13127-0729	1
SHAFT-TRANSMISSION OUTPUT (Ref # 13128)	13128-0715	1
SPROCKET-OUTPUT,15T (Ref # 13144)	13144-0579	1
GEAR,INPUT 2ND,20T (Ref # 13262)	13262-1424	1
GEAR,OUTPUT LOW,39T (Ref # 13262A)	13262-1428	1
GEAR,OUTPUT 2ND,39T (Ref # 13262B)	13262-1429	1
GEAR,INPUT 3RD&4TH,15T&18T (Ref # 13262C)	13262-1482	1
GEAR,OUTPUT 3RD,24T (Ref # 13262D)	13262-1484	1
GEAR,OUTPUT 4TH,25T (Ref # 13262E)	13262-1485	1
GEAR,INPUT 5TH,23T (Ref # 13262F)	13262-1656	1
GEAR,INPUT TOP,29T (Ref # 13262G)	13262-1657	1
GEAR,OUTPUT,5TH,28T (Ref # 13262H)	13262-1658	1
GEAR,OUTPUT,TOP,31T (Ref # 13262I)	13262-1659	1
WASHER,20.5X30X1,STEEL (Ref # 92022)	92022-112	1
BUSHING,OUTPUT,2ND (Ref # 92028)	92028-1739	1
BUSHING,INPUT TOP GEAR (Ref # 92028A)	92028-1915	1
RING-SNAP,20MM (Ref # 92033)	92033-015	2
RING-SNAP,24MM (Ref # 92033A)	92033-026	2
RING-SNAP,T=1.5 (Ref # 92033B)	92033-1249	3
BEARING-BALL,DAC2557NSSH (Ref # 92045)	92045-0003	2
BEARING-NEEDLE,K20X24X13 (Ref # 92046)	92046-0652	1
BEARING-NEEDLE,PK20X27X17X3 (Ref # 92046A)	92046-1303	2
RACE (Ref # 92048)	92048-0016	2
BUSHING,25X28X17.8 (Ref # 92139)	92139-0280	1
BUSHING,OUTPUT,3RD&4TH (Ref # 92139A)	92139-0281	2
COLLAR,SPROCKET (Ref # 92152)	92152-0812	1
WASHER,25.2X31.0X1.5 (Ref # 92200)	92200-1239	2
WASHER,28.5X34.0X1.5 (Ref # 92200A)	92200-1240	3
WASHER,20.5X31X1.5 (Ref # 92200B)	92200-1375	2

2026 Z1100 SE ABS

PARTS LIST

Transmission



ITEM NAME	PART NUMBER	QUANTITY
WASHER,25.8X40.5X1.5 (Ref # 92200C)	92200-1522	1
WASHER,25.2X37.0X1.0 (Ref # 92200D)	92200-1523	1
WASHER (Ref # 92200E)	92200-1720	1
WASHER,22.6X34.2X1.5 (Ref # 92200F)	92200-1941	1
WASHER,22X32X1 (Ref # 92200G)	92200-1942	1
NUT,20MM (Ref # 92210)	92210-0850	1
BALL-STEEL,5/32 (Ref # 600)	600A0500	3