


Mule 600

PARTS DIAGRAM

Shift Lever(s)

F2134



Mule 600

PARTS LIST

Shift Lever(s)

ITEM NAME	PART NUMBER	QUANTITY
BOLT-FLANGED,8X16 (Ref # 130)	130J0816	4
SCREW-PAN-CROS,5X14 (Ref # 220)	220D0514	2
SCREW-PAN-CROSS,5X14 (Ref # 220A)	220F0514	1
NUT-HEX-SMALL (Ref # 318)	318J0800	1
WASHER-PLAIN,8MM (Ref # 411)	411B0800	1
CIRCLIP-TYPE-E,8MM (Ref # 482)	482L8000	2
PIN-SNAP,8MM (Ref # 554)	554A0800	1
PIN-SNAP,10MM (Ref # 554A)	554A1000	1
BRACKET,SHIFT LEVER (Ref # 11053)	11053-1496	1
LEVER (Ref # 13168)	13168-0069	1
LEVER-COMP,SHIFT (Ref # 13236)	13236-0073	1
ARM (Ref # 21083)	21083-0023	1
GRIP (Ref # 46075)	46075-0012	1
GRIP (Ref # 46075A)	46075-0014	1
GRIP,SHIFT (Ref # 46075B)	46075-1185	1
NUT,LOCK,FLANGED,6MM (Ref # 92015)	92015-1675	2
WASHER,10.5X26X2.3 (Ref # 92022)	92022-044	1
SPACER (Ref # 92026)	92026-0074	1
COLLAR,5X7X9.3 (Ref # 92027)	92027-1313	1
BUSHING (Ref # 92028)	92028-1507	4
PIN (Ref # 92043)	92043-0053	1
PIN,10X34 (Ref # 92043A)	92043-1069	1
SPRING (Ref # 92081)	92081-1714	1
SPRING (Ref # 92144)	92144-1510	1
SPRING (Ref # 92145)	92145-0249	1
BOLT,6MM (Ref # 92151)	92151-1747	2
CLAMP (Ref # 92171)	92171-0365	1