


# 1974 MC1-A PARTS DIAGRAM

SWING ARM/SHOCK ABSORBERS ('73-'75 MC1/M)



# 1974 MC1-A PARTS LIST

SWING ARM/SHOCK ABSORBERS ('73-'75 MC1/M)

| ITEM NAME                       | PART NUMBER | QUANTITY |
|---------------------------------|-------------|----------|
| ARM,SWINGING (Ref # 1)          | 33001-055   |          |
| SHAFT,SWING ARM PIVOT (Ref # 2) | 33032-043   |          |
| WASHER PLAIN 12MM (Ref # 3)     | 410B1200    |          |
| BUSH SWING ARM SHAFT (Ref # 4)  | 92092-005   |          |
| WASHER SPRING 12MM (Ref # 5)    | 461F1200    |          |
| NUT-HEX-FINE (Ref # 6)          | 314B1200    |          |
| ADJUSTER CHAIN (Ref # 7)        | 33040-008   |          |
| NUT 6MM (Ref # 8)               | 311B0600    |          |
| WASHER PLAIN 6MM (Ref # 9)      | 410B0600    |          |
| WASHER SPRING 6MM (Ref # 10)    | 461F0600    |          |
| GUARD,CHAIN (Ref # 11)          | 55020-012   |          |
| BOLT-UPSET 6X14 (Ref # 12)      | 112B0614    |          |
| BOLT-UPSET 6X14 (Ref # 12)      | 112B0614    |          |
| NUT 6MM (Ref # 13)              | 311B0600    |          |
| SHOCK ABSBR RR (Ref # 14)       | 45014-100   |          |
| SHOCK ABSBR RR (Ref # 14)       | 45014-100   |          |
| NUT 12MM (Ref # 15)             | 92020-014   |          |
| WASHER PLAIN 12MM (Ref # 16)    | 410B1200    |          |
| WASHER SPRING 12MM (Ref # 17)   | 461F1200    |          |
| BOLT HEX HEAD 10X28 (Ref # 18)  | 113N1028    |          |
| WASHER SPRING 10MM (Ref # 19)   | 461F1000    |          |
| TORQUE LINK,RR BRAKE (Ref # 20) | 43007-037   |          |
| BOLT TORQUE LINK FIT (Ref # 21) | 92003-017   |          |
| BOLT HEX HEAD 10X25 (Ref # 22)  | 92003-003   |          |
| NUT,10MM (Ref # 23)             | 314B1000    |          |
| WASHER SPRING 10MM (Ref # 24)   | 461F1000    |          |
| PIN COTTER 2.0X15 (Ref # 25)    | 550D2015    |          |