



1973 F11 PARTS DIAGRAM

SWING ARM/SHOCK ABSORBERS ('73 F11M)



1973 F11 PARTS LIST

SWING ARM/SHOCK ABSORBERS (73 F11M)

ITEM NAME	PART NUMBER	QUANTITY
SWINGING ARM (Ref # 1)	33001-054	1
SHAFT-SWING ARM PIVOT (Ref # 2)	33032-035	1
CAP-SWINGING ARM (Ref # 3)	33035-005	2
"0" RING,30MM (Ref # 4)	671B2530	9
SLEEVE-SWINGING ARM (Ref # 5)	33034-016	2
BUSHING-SWING ARM (Ref # 6)	33033-009	2
SLEEVE-SWING ARM,LON (Ref # 7)	33034-018	1
"0" RING,16MM (Ref # 8)	670B2016	2
NUT,12MM (Ref # 9)	92019-017	1
ADJUSTER-CHAIN (Ref # 10)	33040-050	2
PLATE, CHAIN ADJUSTER (Ref # 11)	33041-002	2
NUT 6MM (Ref # 12)	312B0600	4
UNAVAILABLE IN PRICE BOOK (Ref # 13)	55020-010	1
ROLLAR (Ref # 14)	92122-002	1
COLLAR (Ref # 15)	92027-192	1
BOLT 6X35 (Ref # 16)	110R0635	1
BOLT-UPSET,6X35 (Ref # 16)	112G0635	AL
NUT (Ref # 17)	92019-008	1
BOLT-UPSET,6X12 (Ref # 18)	112G0612	2
BOLT-UPSET,6X12 (Ref # 18)	112G0612	AL
WASHER PLAIN 6MM (Ref # 19)	410B0600	2
WASHER SPRING 6MM (Ref # 20)	461F0600	2
SHOCK ABSBR RR (Ref # 21)	45014-086	2
NUT,10MM (Ref # 22)	92019-016	4
WASHER-PL-10.5X26X2. (Ref # 23)	92022-044	3
WASHER PLAIN 12MM (Ref # 24)	410B1200	2