


## Driven Converter/Drive Belt



## 2024 MULE PRO-FXR 1000 PARTS LIST

### Driven Converter/Drive Belt

| ITEM NAME                           | PART NUMBER | QUANTITY |
|-------------------------------------|-------------|----------|
| SEAT-SPRING,MOVABLE (Ref # 16007)   | 16007-0049  | 1        |
| SEAT-SPRING,FIXED (Ref # 16007A)    | 16007-0050  | 1        |
| CONVERTER-ASSY-DRIVEN (Ref # 49094) | 49094-0102  | 1        |
| BELT,CVT (Ref # 59011)              | 59011-0056  | 1        |
| SHEAVE-COMP,MOVABLE (Ref # 59302)   | 59302-0110  | 1        |
| SHEAVE-COMP (Ref # 59302A)          | 59302-0111  | 1        |
| SPACER,T=0.30 (Ref # 92026)         | 92026-0034  | AR       |
| SPACER,T=1.00 (Ref # 92026A)        | 92026-1565  | AR       |
| SPACER,T=0.60 (Ref # 92026B)        | 92026-1569  | AR       |
| SPACER,T=1.40 (Ref # 92026C)        | 92026-1570  | AR       |
| SPACER,T=0.80 (Ref # 92026D)        | 92026-1617  | AR       |
| RING-SNAP (Ref # 92033)             | 92033-1317  | 1        |
| SEAL-OIL (Ref # 92049)              | 92049-1528  | 2        |
| RING-O,46.4X3.1 (Ref # 92055)       | 92055-0752  | 1        |
| RING-O,59.5X2.4 (Ref # 92055A)      | 92055-0753  | 1        |
| ROLLER (Ref # 92122)                | 92122-0043  | 4        |
| BUSHING (Ref # 92139)               | 92139-0313  | 2        |
| SPRING (Ref # 92145)                | 92145-1577  | 1        |
| BOLT,FLANGED,12X55 (Ref # 92154)    | 92154-1336  | 1        |
| WASHER (Ref # 92200)                | 92200-0069  | 1        |
| O RING (Ref # 671)                  | 671D2530    | 1        |