


Labels(CN)

Let the Good Times Roll®


56071E



56071A




56071F



NOTICE

Vehicle must be stopped before shifting transmission. Shifting while moving may result in transmission damage.




560711



IMPORTANT DRIVE BELT INFORMATION
Always, always, use proper technique to wear the seat belt. The transmission drive belt is not designed for failure. Inspection of the transmission drive belt is required at least every 3000 km (1800 mi) or prior to each subsequent repair that involves belt drive power with several km.
Use frequent inspection is necessary if the vehicle is subjected to hard usage. If unusual belt slippage occurs, do not lose the vehicle until properly diagnosed.
Do not attempt to drive on worn drive belts. When not




56071C




56071G

56071P




56071K



56071

56071L




56071R


56071D




56071B




56071N




560710




56030A



56071H



56071M



-56071Q

2021 BRUTE FORCE® 300

PARTS LIST

Labels(CN)



ITEM NAME	PART NUMBER	QUANTITY
-----------	-------------	----------