

Air Cleaner

Let the Good Times Roll®

Exploded view diagram of the front suspension assembly, showing various components and their assembly sequence. The diagram includes a "FRONT" arrow indicating the orientation.

Key components and assembly steps shown:

- 92170**: Lower control arm ball joint.
- 92192C**: Lower control arm.
- 16126**: Lower control arm bushing.
- 92170**: Lower control arm ball joint (second instance).
- 92192**: Lower control arm.
- 92173B**: Lower control arm bushing.
- 92173C**: Lower control arm bushing.
- 92161**: Lower control arm ball joint.
- 92172A**: Lower control arm ball joint.
- 11038**: Lower control arm bushing.
- 11065**: Lower control arm bushing.
- 92093A**: Lower control arm bushing.
- 92172**: Lower control arm ball joint.
- 92093**: Lower control arm bushing.
- 13280**: Lower control arm bushing.
- 11013**: Lower control arm bushing.
- 13280A**: Lower control arm bushing.
- 92173A**: Lower control arm ball joint.
- 92192A**: Lower control arm.
- 92173**: Lower control arm bushing.
- 92173D**: Lower control arm bushing.
- 92192B**: Lower control arm.
- 92161A**: Lower control arm ball joint.

The diagram also shows the assembly of the lower control arm into the vehicle frame, with labels like "Ref. Frame" and "A" indicating specific points of interest.

2023 Versys-X 300

PARTS LIST

Air Cleaner



ITEM NAME	PART NUMBER	QUANTITY
-----------	-------------	----------